

序号	报告编号	发布日期	结论	影像资料
66	GX-B1466/22-B-24063-24072	2024.8.8	所检项目合格	 A photograph showing two technicians in a laboratory setting. One technician is looking at a mobile device while the other is working with equipment inside a fume hood. The date '2024.7.12' is overlaid in the bottom right corner. 2024.7.12
67	GX-B1410/22-B-24242	2024.8.8	所检项目合格	 A photograph showing two technicians in a laboratory setting. One technician is looking at a mobile device while the other is working with equipment inside a fume hood. The date '2024.7.22' is overlaid in the bottom right corner. 2024.7.22

68	GX-B1601/22-B-240448~240454	2024.8.9	所检项目合格	
69	GX-B1601/22-B-240411~240427	2024.8.9	所检项目合格	
70	GX-B1601/22-B-240470~240472	2024.8.9	所检项目合格	

71	GX-B1601/22-B-240445~240446	2024.8.9	所检项目合格	
72	GX-B1372/22-B-240580~240588	2024.8.8	所检项目合格	
73	GX-B1475/22-B-240160	2024.8.8	所检项目合格	

74	GX-B1374/22-B-240502~240508	2024.8.8	所检项目合格	 <p>2024.6.25</p>
75	GX-B1410/22-B-24224~24230	2024.8.8	所检项目合格	 <p>2024.7.13</p>
76	GX-B1601/22-B-240394~240396	2024.8.13	所检项目合格	 <p>2024.6.28</p>

77	GX-B1373/21-B-24300~24304	2024.8.9	所检项目合格	
78	GX-B1412/22-B-24022	2024.8.9	所检项目合格	
79	GX-B1411/22-B-24092	2024.8.9	所检项目合格	

80	GX-B1409/22-B-24043~24045	2024.8.15	所检项目合格	
81	GX-B1372/22-B-240591~240603	2024.8.8	所检项目合格	
82	GX-B1374/22-B-240539~240542	2024.8.8	所检项目合格	

83	GX-B1465/22-B-24112~24113	2024.8.12	所检项目合格	 <p>2024.7.17</p>
84	GX-B1601/22-B-240473~240474	2024.8.12	所检项目合格	 <p>2024.7.21</p>
85	GX-B1603/22-B-240269	2024.8.12	所检项目合格	 <p>2024.7.22</p>

86	GX-B1373/21-B-24362~24371	2024.8.12	所检项目合格	 A male technician in a grey uniform with '中检公信' on the back is standing next to a female inspector in a grey uniform. They are looking at a piece of equipment on a lab bench. The date '2024.7.23' is visible in the bottom right corner of the photo. <p>2024.7.23</p>
87	GX-B1374/22-B-240556~240561	2024.8.8	所检项目合格	 A male technician in a grey uniform is working inside a laboratory fume hood. A female inspector in a grey uniform is standing next to him, observing the work. The date '2024.7.30' is visible in the bottom right corner of the photo. <p>2024.7.30</p>
88	GX-B1372/22-B-240623~240629	2024.8.8	所检项目合格	 A male technician in a grey uniform is looking at a piece of equipment on a lab bench. A female inspector in a grey uniform is standing next to him, looking at the equipment. The date '2024.7.30' is visible in the bottom right corner of the photo. <p>2024.7.30</p>

89	GX-B1373/21-B-24357~24361	2024.8.12	所检项目合格	 <p>2024.7.21</p>
90	GX-B1374/22-B-240570~240571	2024.8.13	所检项目合格	 <p>2024.7.24</p>
91	GX-B1374/22-B-240562-240569	2024.8.13	所检项目合格	 <p>2024.7.20</p>

92	GX-B1372/22-B-240647-240648	2024.8.13	所检项目合格	
93	GX-B1475/22-B-240206	2024.8.13	所检项目合格	
94	GX-B1372/22-B-240630~240646	2024.8.13	所检项目合格	

95	GX-B1372/22-B-240676~240677	2024.8.13	所检项目合格	
96	GX-B1374/22-B-240575~240593	2024.8.13	所检项目合格	
97	GX-B1410/22-B-24253~24260	2024.8.13	所检项目合格	

98	GX-B1601/22-B-240479~240484	2024.8.12	所检项目合格	 <p>2024.8.1</p>
99	GX-B1606/23-B-24068~24077	2024年8月13日	所检项目合格	 <p>2024.7.14</p>
100	GX-B1606/23-B-24078~24084	2024年8月14日	所检项目合格	 <p>2024.7.15</p>

101	GX-B1606/23-B-24090	2024年8月14日	所检项目合格	
102	GX-B1605/23-B-24068-24077	2024年8月14日	所检项目合格	
103	GX-B1605/23-B-24078-24084	2024年8月14日	所检项目合格	

104	GX-B1605/23-B-24090	2024年8月14日	所检项目合格	 A photograph showing two technicians in light blue uniforms working in a laboratory. One technician is holding a handheld device, and the other is looking at a piece of equipment. The date stamp '2024.7.13' is visible in the bottom right corner of the image.
105	GX-B1604/23-B-24003	2024.8.14	所检项目合格	 A photograph showing two technicians in light blue uniforms working in a laboratory. One technician is holding a handheld device, and the other is looking at a piece of equipment. The date stamp '2024.7.23' is visible in the bottom right corner of the image.