


序号	报告编号	发布日期	结论	影像资料
94	GX-B1522/20-P-24004	2024. 8. 23	所检项目合格。	
95	GX-B1522/20-P-24005	2024. 8. 23	所检项目合格。	
96	GX-B1539/22-P-24003	2024. 8. 26	所检项目合格。	

97	GX-B1539/22-P-24004	2024. 8. 26	所检项目合格。			
98	GX-B1539/22-P-24005	2024. 8. 26	所检项目合格。			
99	GX-B1380/20-P-24002	2024. 8. 27	所检项目合格。			

100	GX-B1380/20-P-24003	2024. 8. 27	所检项目合格。		
101	GX-B1380/20-P-24004	2024. 8. 27	所检项目合格。		
102	GX-B1382/21-P-24008	2024. 8. 27	综合判定:合格。		

103	GX-B1310/21-P-24064	2024. 8. 27	符合标准要求。		 A worker wearing a red hard hat and safety harness is positioned on a high-altitude steel structure, likely part of a large industrial machine or tower. The structure is made of dark metal beams and ladders. The background shows a clear sky and some distant buildings. 2024.7.26	
104	GX-B1310/21-P-24065	2024. 8. 27	符合标准要求。		 A worker wearing a red hard hat and safety harness is inspecting a large, green, curved component of a machine. The worker is holding a yellow spray bottle and a black bag. The component has several bolts and a red section. The background shows an indoor industrial setting with windows. 2024.7.26	
105	GX-B1310/21-P-24066	2024. 8. 27	符合标准要求。		 A worker wearing a red hard hat and safety harness is working on a platform. The worker is holding a black bag and a yellow spray bottle. The platform is made of metal and has a red safety rope. The background shows an outdoor industrial setting with a clear sky and some distant buildings. 2024.7.26	

106	GX-B1427/21-P-24008	2024. 8. 27	符合标准要求。	
107	GX-B1522/20-P-24001	2024. 8. 28	所检项目合格。	
108	GX-B1522/20-P-24002	2024. 8. 28	所检项目合格。	

109	GX-B1522/20-P-24003	2024. 8. 28	所检项目合格。	
110	GX-B1522/20-P-24006	2024. 8. 28	所检项目合格。	
111	GX-B1522/20-P-24007	2024. 8. 28	所检项目合格。	

112	GX-B1404/20-P-24024	2024. 8. 30	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	
113	GX-B1404/20-P-24025	2024. 8. 30	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	